

Calais at Pelican Bay

Project Management Report – Building E

1. Unit E301 Interior Structural Slab Crack Repair

Socotec conducted a field inspection of the ongoing structural crack repair at Unit E301 on November 25th and 26th, 2025, and a final inspection on December 3rd, 2025. This report certifies that the structural crack repair work and waterproofing installation have been completed and inspected at the above-referenced location. The work has been executed in general accordance with our engineering specifications and instructions, and the waterproofing has been installed per manufacturer specifications.





Observed completed interior structural slab crack repair.