

PRE-INSPECTION REPORT

Project Name: Calais at Pelican Bay


Date: June 27, 2019

Supervisor: H. Torres

R = Rear, F = Front, RS = Right Side, LS = Left Side

Bldg. / Drop	Unit #	Floor	Location	Photo #	Comments:
7000 (A)	204		F	1-2	Damaged Garage Door Trim
7016 (G)	104		RS	3-5	Damaged Vent by Entry Door
7008 (H)	501		F	6-7	Damaged Railing Picket by Unit 501
	104		F	8	Damaged Ceiling Vent
			F	9	Damaged Handrail Cap by Ground Floor Meter Room
			R	10	Damaged Light Fixture
7024 (F)	204		F	11	Damaged Floor Tile by Unit 204
	202		F	12	Damaged Floor Tile by Unit 202
			F	13	Damaged Door Frame at Trash Chute (1st Floor)
7032 (E)	205		F	14-15	Damaged Garage Door Trim
			F	16	Rusted Door / Frame at Garbage Room
	301		F	17-20	Damaged Floor Tile at Unit 301
				21	Damaged Floor Tile/Grout by Elevator & Unit 304
	304		F	22	Damaged Tile in Corner
	305		F	23	Damaged Floor Tile by Unit 305 & Stairway
7040 (D)	504		F		Damaged Floor Tile at Unit 504
					Damaged Floor Tile by 3rd Floor Trash Chute
	102		F		Damaged Floor Tile By Unit 102
					Damaged Floor Tile by Meter Room at Rail Post
					Damaged Floor Tile at Main Entry to Building
7048 ©	301		F		Damaged Floor Tile by Unit 301 & Stairway
	305		F		Damaged Floor Tile at Stairway

Please review, sign in the area marked and return via fax or email.



X Signature